

**2.6.2 2005 Professional and Do-It-Yourself Improvements, by Project (\$2006)**

	Professional Installation			Do-It-Yourself Installation		
	Homeowners	Total	Mean	Homeowners	Total	Mean
<u>Repair/Improvement</u>	<u>(millions)</u>	<u>Expenditures</u>	<u>Expenditures</u>	<u>(thousands)</u>	<u>Expenditures</u>	<u>Expenditures</u>
		<u>(\$billion)</u>	<u>(\$)</u>		<u>(\$billion)</u>	<u>(\$)</u>
Disaster Repairs	0.61	9.0	14,398	0.20	1.3	6,698
Kitchen Remodeled	1.13	13.4	11,550	1.05	5.7	5,411
Additions Built	1.27	30.4	23,212	1.38	9.3	6,767
Bathroom Remodeled or Added	1.13	8.8	7,527	1.34	3.8	2,852
Exterior Improvements	3.85	23.7	5,983	3.11	7.9	2,527
Siding Replaced or Added	0.82	5.3	6,322	0.39	1.0	2,583
Roof Replacement	2.67	14.5	5,281	0.81	1.9	2,366
HVAC Replacement	2.44	7.3	2,895	0.51	1.5	2,909
Windows/Doors Installed	2.53	7.8	2,995	1.72	2.6	1,501
Flooring/Paneling/Ceiling Replacement	4.65	12.7	2,661	3.48	4.2	1,221
Electric System Replacement	1.35	1.6	1,144	0.89	0.4	451
Plumbing Replacement	0.84	1.5	1,726	2.08	1.0	467
Insulation Added	0.59	1.4	2,361	0.72	1.1	1,513
Appliance/Major Equipment Replacement	3.59	2.4	657	2.49	1.0	385

Note(s): Expenditures are \$39.1 billion higher in Table 2.6.1. This discrepancy is due to sampling methods used by HUD for the American Housing Survey and DOC in the Survey of Expenditures for Residential Improvements and Repairs.

Source(s): Joint Center for Housing Studies of Harvard University, Improving America's Housing 2007, Feb. 2007, Table A-2, p. 28.